

SECRET

7 May 1963

MEMORANDUM FOR: Assistant for Operations

SUBJECT: Evaluation of "B" Photography

Mission No.	Date Flown	Camera Number	Processed By
3591	6 May 1963	13	Navy PIC

REMARKS:

1. The shutter malfunctioned on Mission 3591, beginning with titled frame 200. On frame 200 and 201 the shutter remained open. It operated correctly on frame 202; however, on frame 203 it closed and remained in that position thereafter, terminating the effectiveness of the mission.

2. It is recommended that the operating unit be notified of the nature of this malfunction.

25X1A



Chief, Technical Intelligence Division

Distribution:

Orig - Addressee  
2 - TID  
1 - TSB Eval 1A  
1 - TSB Chrono

NPIC/TID/TSB [redacted] sch/3305

25X1A

DOCUMENT NO. \_\_\_\_\_  
NO CHANGE IN CLASS. ☐  
☐ DECLASSIFIED  
CLASS. CHANGED TO: TS S **2012**  
NEXT REVIEW DATE: \_\_\_\_\_  
AUTH: HP 7-2  
DATE: **25 MAY 1988** REVIEWER: **0109599**

SECRET